

JHA LIBRARY

Hazards for the lift. Crane, signals, rigging, the plan. Open the one for this work. Do the work to the SWP.

Rev 01 Effective 2026-09-01 Review 2027-09-01 Printed copy uncontrolled

What can hurt you. What holds the risk.

SWP - the method. Numbered steps.

JHA - the hazards for the same work. These pages.

SJP - this morning. This table, this deck, this serial.

Each row carries a badge. Extreme is no recovery - people under the load, MAD, a table over the edge. High is serious injury or a dropped load. They are not the same badge. If a stop is named, the job does not proceed.

03 - HAZARD ASSESSMENT -> <https://sin.ae.org/safety/hazard-assessment>

14 - SWP LIBRARY -> <https://sin.ae.org/safety/swp-library>

16 - SJP LIBRARY -> <https://sin.ae.org/safety/sjp-library>